



2	Führungen	1	Q. 8		
2	Fingerring	2	Fl. 8		stump. best.
2	Feder	3	St.		stump. best.
2	Schrauben	4	Fl. 8		
2	Mutter 1 1/2"	5	" "		
2	Spalte 10mm	6	" "		
2	Spalten	7	" "		sperrt. best.
8	Schrauben 1/8"	8	" "		
8	Mutter "	9	" "		
8	Spalte 6mm	10	" "		
2	Schrauben		" "		stump. best.

Fingerring.

