



3	Spændestyl 25x4x4	N	215E
1	Forbindelse 6F 0.5-30	K	Kobber
7	Sikringsblek 3/8"	g	100D
2	Møtrik 7/8"	f	58 F
2	Skruer 3/8"	e	4 F
32	Sikringsblek 7/8"	d	100B
16	Møtrik 3/4"	c	58 F
16	Skruer 1/2"	b	4 F
2	Sikringsblek 3/16"	a	100C
2	Tape 5/16"	ø	121 E
2	Møtrik 1/16"	E	58 E
2	Isolation 0.2	Z	Isolerbaand
2	Isolation 0.5	J	Freskvar
4	Federaksler 1/16"	T	589 E
4	Skruer 1/16"	W	161 M
14	Sikringsblek 3/8"	V	100B
14	Skruer 1/8"	U	4 E
8	Sikringsblek 1/4"	T	100B
4	Møtrik 1/4"	S	58 D
4	Skrue 1/4"	R	212
4	Isolatorspl. 1/4" x 3/8"	Q	Freskvar
2	Klods	P	Olieagtigt Sigtetv
6	Klods	O	
12	Klods	N	Olieagtigt Sigtetv
1	Spændestyl 25x4x4	N	215E
3	25x4x4	L	
6	15x4x4	K	
6	Spændestyl 25x4x4	J	215E
2	Klemblek	H	58 F 4/32
2	Klemme	G	58 F 4/32
2	Forbindelse 0.5-30	F	Kobber
4		E	
1	Forbindelse 0.5-30	D	
4	Kabelsko	C	Rør 1 1/2"
2	Kabel 1.5x2.5	B	2000